# Schneider Electric

# Dew Point Control Pump Kit—Installation

## Inventory



Item	Description	Quantity	Item	Description	Quantity
0	Bracket, pump clamp	1	B	Pipe connection insulation	1
2	Water circulation pump	1	14	Pump connection insulation	2
B	M6 × 12 T20 screw	6	G	Check valve insulation	1
4	M4 × 8 TORX	6	16	Bracket	1
6	M4 × 8 TORX w/ washer	2	Ū	Pump clamp	1
6	Pipe union gasket	3	18	Tee assembly	1
0	Pump union gasket	2	Ð	Pump clamp Insulation	1
8	Circulation pump insulation	1	20	Upper piping bracket	1
9	Check valve insulation	1	2	Wire harness	1
Ū	1-3/8 in. cushion clamp	1	22	Pump user manual	1
0	Check valve assembly	1	æ	Wire tie	12
Ð	Pipe, 1-1/8 in.	1	24	Connector mounting bracket	1

# **Tools Required**





# Safety

## A A DANGER

HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH

Turn off all electrical power before working on or near this equipment.

Failure to follow these instructions will result in death or serious injury.

## **ACAUTION**

### SHARP EDGES

Wear protective gloves during assembly.

Failure to follow these instructions can result in minor or moderate injury

## **A**WARNING

#### TIP HAZARD

Risk of tip hazard during assembly. Be sure to secure unit or use two people during the assembly process.

Failure to follow these instructions can result in death or serious injury.

# Installation

**NOTE:** Some parts not shown for better visibility of the installation process.



















P









Customer support and warranty information is available at the APC Web site, www.apc.com.